



GV2ME●●

GV2AF01 / GV2AF3
LC1K●● / LC1D●●

1,7 N.m
15 lb.in

1 N.m 7 lb.in
1,7 N.m 15 lb.in
2,5 N.m 20 lb.in

LC1K
LC1D9/12/18
LC125/32

Ø 6 mm

GV1G09 GV2G4●●

www.schneider-electric.com/site/home

1672546

1cc >>

GVAM11

GV2ME●●
04 - 2016

Schneider Electric Industries SAS
35, rue Joseph Monier
92506 Rueil Malmaison
France

www.schneider-electric.com
W9 1645571 0211-08

	mm AWG	mm in	N.m lb-in
x1	1.6	1/16	1.7
x2	1.8...10	3/32	15
x1	1.5...6	1/16	10
x2	1.6...10	3/32	15
x1	1.4	1/16	1.7
x2	1.8...10	3/32	15

Click!

TEST

Ø 3 mm
1/8 inch

≤ Ø 3 mm
1/16 inch

⚠️ ⚠️ DANGER / 危险

HAZARD OF ELECTRIC SHOCK, EXPLOSION, OR ARC FLASH

Disconnect all power before servicing equipment.
Failure to follow these instructions will result in death or serious injury.

电击、爆炸或电弧闪光危险
 在此电力设备上进行操作时，请先断开所有电源
 不遵循上述规定将可能导致人员伤亡。

