



1

Click!

2

GV2ME●●

GV2AF01 / GV2AF3
LC1K●● / LC1D●●

4

5

1,7 N.m
15 lb.in

GV1G09

GV2G4●●

www.schneider-electric.com/site/home

1672546

1

2

1

2

3

LC1K 1 N.m 7 lb.in
LC1D9/12/18 1,7 N.m 15 lb.in
LC125/32 2,5 N.m 20 lb.in

Ø 6 mm

GVAM11

1

2

lcc >>

Schneider Electric Industries SAS
35, rue Joseph Monier
92506 Rueil Malmaison
France

www.schneider-electric.com
W9 1645571 0211-08

GV2ME●●
04 - 2016

In

	mm AWG	mm in	N.m lb-in
x1	1...6	18...10	1,7
x1 x2	1,5...6	10	3/8
x1	1...4	18...10	
x1 x2	1,4...10	18...10	

Click!

TEST

Ø 3 mm
1/8 inch

STOP

Click!

TEST

Ø 3 mm
1/8 inch

Click!

TEST

≤ Ø 3 mm
1/16 inch

⚠ ⚠ DANGER / 危险

HAZARD OF ELECTRIC SHOCK, EXPLOSION, OR ARC FLASH

Disconnect all power before servicing equipment.
Failure to follow these instructions will result in death or serious injury.

电击、爆炸或电弧闪光危险
在此电力设备上进行操作时，请先断开所有电源
不遵循上述规定将可能导致人员伤亡。

